

簡易電子測距基線場檢測紀錄表

| 檢測單位：新北市三重地政事務所 | | 地點：新北市三重區過圳公園北側人行道 | | | 日期：106年6月21日 | |
|-------------------|------|--------------------|---------|---------|----------------|---------|
| 儀器廠牌：SOKKIA | | 型號：CX-103 | | | 序號：BD0258 | |
| 精度規格：2.0mm±2.0ppm | | 溫度：25°C | | | 壓力：1006 百帕(毫巴) | |
| 儀器站 | 稜鏡站 | 正鏡1 | 倒鏡1 | 正鏡2 | 倒鏡2 | 總平均 |
| 0m | 5m | 4.9966 | 4.9966 | 4.9966 | 4.9966 | 4.9966 |
| | | 4.9963 | 4.9966 | 4.9966 | 4.9966 | |
| | | 4.9966 | 4.9966 | 4.9966 | 4.9966 | |
| 0m | 23m | 22.9999 | 22.9999 | 22.9999 | 22.9999 | 22.9998 |
| | | 22.9996 | 22.9999 | 22.9989 | 22.9999 | |
| | | 22.9999 | 22.9999 | 22.9999 | 22.9999 | |
| 0m | 31m | 31.0018 | 31.0028 | 31.0028 | 31.0028 | 31.0027 |
| | | 31.0025 | 31.0028 | 31.0028 | 31.0028 | |
| | | 31.0028 | 31.0028 | 31.0028 | 31.0028 | |
| 0m | 59m | 58.9996 | 58.9996 | 58.9995 | 58.9996 | 58.9996 |
| | | 58.9993 | 58.9996 | 58.9995 | 58.9996 | |
| | | 58.9996 | 58.9996 | 58.9995 | 58.9996 | |
| 0m | 77m | 77.0046 | 77.0046 | 77.0036 | 77.0046 | 77.0042 |
| | | 77.0039 | 77.0036 | 77.0039 | 77.0046 | |
| | | 77.0036 | 77.0039 | 77.0043 | 77.0046 | |
| 0m | 95m | 95.0097 | 95.0095 | 95.0097 | 95.0094 | 95.0096 |
| | | 95.0104 | 95.0095 | 95.0094 | 95.0094 | |
| | | 95.0094 | 95.0095 | 95.0094 | 95.0101 | |
| 0m | 143m | | | | | |
| 0m | 266m | | | | | |
| 5m | 23m | 18.0030 | 18.0030 | 18.0030 | 18.0030 | 18.0030 |
| | | 18.0030 | 18.0030 | 18.0030 | 18.0030 | |
| | | 18.0030 | 18.0030 | 18.0030 | 18.0030 | |
| 5m | 31m | 26.0039 | 26.0039 | 26.0039 | 26.0049 | 26.0042 |
| | | 26.0042 | 26.0049 | 26.0042 | 26.0042 | |
| | | 26.0042 | 26.0039 | 26.0039 | 26.0039 | |
| 5m | 59m | 54.0016 | 54.0023 | 54.0016 | 54.0016 | 54.0018 |
| | | 54.0016 | 54.0019 | 54.0016 | 54.0016 | |
| | | 54.0016 | 54.0026 | 54.0016 | 54.0019 | |
| 5m | 77m | 72.0063 | 72.0066 | 72.0066 | 72.0066 | 72.0064 |
| | | 72.0056 | 72.0069 | 72.0059 | 72.0066 | |
| | | 72.0063 | 72.0066 | 72.0059 | 72.0066 | |
| 5m | 95m | 90.0115 | 90.0125 | 90.0115 | 90.0125 | 90.0118 |
| | | 90.0115 | 90.0125 | 90.0115 | 90.0118 | |
| | | 90.0115 | 90.0118 | 90.0115 | 90.0115 | |
| 5m | 143m | | | | | |
| 5m | 266m | | | | | |
| 檢測人員：技士楊志成 | | 檢查人員：技士洪培原 | | | | |